

Product Bulletin

TO: All Valued Beck/Arnley Customers
FROM: Product Management
DATE: August 6, 2010
SUBJECT: Fuel Injector Core Returns


2010-10-CSB-AL

When processing Fuel Injector core returns, please review the following images and conditions to make sure that your core does not have any of the following damage. We cannot accept fuel injector cores in the following conditions:


Core is burnt or has body damage.



Any clip or piece is missing from the fuel injector.




A pintle is missing or a core with any rust damage.



Fuel Injector has sustained cracks or any burn damage.



Fuel injector is missing its retainer clip.



To return items, please contact your Beck/Arnley sales rep. They will provide you with a return claim form if you do not already have one.