

Beck/Arnley

Ignition Coil Boots

“Coil On Plug” Technology

- Many modern engines are now equipped with “coil on plug” technology (each spark plug has its own separate ignition coil). This coil is connected directly to the spark plug by a rubber boot.
- Until now, if the ignition coil boot or resistor failed, the only option was to replace the entire coil.
- But there are a number of applications where the ignition coil boot and resistor can be removed and replaced with a completely new boot and resistor.

Expensive Repair

Economical Beck/Arnley Repair



An Economical Alternative To An Expensive Repair!

- These new ignition coil boots, including the resistor, are now available from Beck/Arnley at a fraction of the cost of a new coil and boot assembly.
- They are priced one (1) to a box and can be ordered depending on actual vehicle needs.

Sample Applications

MVQ	Part #	Application
6	175-1016	HonTrk:Passport(2000-2002), IsuTrk:Amigo(2000), Axiom(2002-2003), Rodeo(2000-2004), Rodeo Sport (2001-2003), Trooper(2000-2002)
6	175-1017	ToyTrk:4 Runner(1996-2002), T100(1995-1996), Tacoma(1995-2004), Tundra(2000-2004)
6	175-1019	Nis:Maxima(1995-2000)

